




131 Tuliptree
Sections have
Collapsed.

Completed 135,139,143 Tuliptree
during Phase 1

155 Tuliptree
Sections have
Collapsed.

Braced sections
during Phase 1, 159
Tuliptree replacement
required



				NOTES/LEGEND		DRAFTING			Tuliptree Sound Barrier CITY OF THOROLD	CONSULTANT FILE No.			
				1 THE POSITION OF POLE LINES, CONDUITS, WATERMANS, SEWER AND OTHER UNDERGROUND UTILITIES AND STRUCTURES IS NOT NECESSARILY SHOWN ON THE CONTRACT DRAWINGS AND, WHERE SHOWN, THE ACCURACY OF THE POSITION OF SUCH UTILITIES AND STRUCTURES IS NOT GUARANTEED. BEFORE STARTING WORK, THE CONTRACTOR SHALL INFORM HIMSELF OF THE EXACT LOCATION OF ALL SUCH UTILITIES AND STRUCTURES AND SHALL ASSUME ALL LIABILITY FOR DAMAGE TO THEM.		C.V				DATE	2018-08-27		
				2 PROPERTY LINES WERE PLOTTED USING REGISTERED PLANS AND BARS LOCATED IN THE FIELD. TO VERIFY THE ACCURACY OF THESE PROPERTY LINES, A LEGAL SURVEY SHOULD BE PERFORMED PRIOR TO CONSTRUCTION.		DESIGN				SCALE	Hor : 1:100 m Ver :		
						CHECKED BY				REF. No.			
						APPROVED BY				DWG No.			
no.	REVISION	DATE	INIT.			S.W.D				REV.			
0													